

DATE



Executive Flight Services, Inc.
151 Texas Way
Fort Worth, TX 76106
Phone: (817) 740-9904 Fax: (817) 740-9906



Make: **Beechcraft** Model: **A36** Serial No: **E-959** Reg. No. **N4260S**
Hobbs: **5143.3** Tach: **5467.7** Date: **05 Jun 2009**

Removed Prestolite starter P/N MCL6501, S/N H012400 and installed Kelly Aerospace starter P/N MCL-6501R S/N J020181 (overhauled by Kelly Aerospace, Montgomery, Alabama, on W/O M100120), in accordance with Beechcraft Bonanza 36 Series Shop Manual Chapter 13.
Installed Altitude Gyro Indicator P/N C661076-0103 S/N 1166 in accordance with Beechcraft Bonanza 36 Series Shop Manual after overhaul by Castleberry Instruments & Avionics, LLC, Austin Texas on work order 017359 dated 5/26/2009.

I certify this aircraft has been repaired and inspected in accordance with the current Federal Aviation Regulations and is approved for return to service for the above work accomplished.

Signature

James A. Brooks

Certificate # **A&P 523476442**



EXECUTIVE AIRSHARE CORPORATION
1600 Airport Road - Mid-Continent Airport
Wichita, Kansas 67209-1996 USA

Make: BEECH Model: A36 S/N: E-959 Reg: N4260S
ACTT: 5493.9 Hobbs: 5169.1

COMPLETED THE FOLLOWING INSPECTIONS:

- 100 Hr/Annual inspection I.A.W. Beech M.M.
- ELT inspection per FAR PART 91.207 (d). No defects noted
- AD 2007-08-08 Inspected and lubed up-lock rollers. No defects noted
- SI 0558-412 Heat exchanger pressure checks/periodic inspection. No defects noted

PERFORMED THE FOLLOWING MAINTENANCE:

- 50 Hr Engine oil & filter change. Serviced with Phillips 66 X/C 20W-50. Oil filter P/N CH 48109-1. Ground run & leak checks were satisfactory.
- Installed New ELT battery P/N NARCO 10. Ops checks good.
- Installed New induction air filter P/N BA7112. Ops checks good.
- Installed New vacuum system filters: P/N RA-D-9-14-5 & RA1J4-7. Ops checks good.
- Installed New subpanel lights inverter P/N 71254-7. Ops checks good.
- Installed New aileron trim control assembly P/N 35-380072-1. Ops checks good.
- Installed New L/H & R/H MLG brake pads P/N 066-10500. Ops checks good.
- Installed New NLG tire P/N 071-312-0 S/N 4118W00234. Leak checks good.
- Installed New NLG bungee rod ends P/N 131553-4M & 35-825162, new steering link P/N 35-825035. Ops checks good.
- Installed New L/H & R/H MLG drag leg center bolts P/N 35-815274-1, new bushings P/N 35-810122-1. Ops checks good.
- Installed New L/H MLG door link assembly P/N 35-815007-4, new bolts P/N 130909B84 & 130909B41, new bushings P/N 58-810015-1. Ops checks good.
- Installed New shimmy dampner barrel P/N 35-825146-2, new o-rings P/N M83461/1-006, M83461/1-012, M83461/1-115. Ops & leak checks good.
- Installed New NLG wheel assembly P/N 40-77E. Leak checks good

I certify this Aircraft has been inspected in accordance with 100 Hr Annual inspection, in accordance with the current Federal Aviation Regulations was determined to be in airworthy condition and is approved for return to service

Signed:

W O No. 7092 CRS No. XMNR954Y Date: 7-10-09



TOTAL—Carry forward to next page

AIRFRAME



EXECUTIVE AIRSHARE CORPORATION
1600 Airport Road - Mid-Continent Airport
Wichita, Kansas 67209-1996 USA

Make: BEECH Model: A36 S/N: E-959 Reg: N4260S
ACTT: 5335.0 Hobbs: 5006.7 PTT: 306.0

COMPLETED THE FOLLOWING INSPECTIONS:
100 Hr/Annual inspection I.A.W. Beech M.M.

PERFORMED THE FOLLOWING MAINTENANCE:

Installed Overhauled Engine P/N IO-520-BA S/N 249720-R ETT 3625.3 TSOH 0.0
Removed & Installed propeller I.A.W. M.M. Ops checks and leak checks were satisfactory.
Rigged Engine controls I.A.W. M.M. ground runs and leak checks were satisfactory.
Installed New engine control rod ends P/N 131765-1F. New bolts P/N 130909B8. New nuts P/N 130909N3.
Installed Overhauled engine propeller governor P/N D210680 S/N 1194664. Ops checks good.
Installed New engine propeller control cable P/N 35-944048-3. Ops checks good.

I certify this Propeller has been inspected in accordance with 100 Hr/Annual inspection, in accordance with the current Federal Aviation Regulations was determined to be in airworthy condition and is approved for return to service.

Signed: [Signature] W/O No. 30816 CRS No. MXMR954Y Date: 6-1-08



EXECUTIVE AIRSHARE CORPORATION
1600 Airport Road - Mid-Continent Airport
Wichita, Kansas 67209-1996 USA

Make: BEECH Model: A36 S/N: E-959 Reg: N4260S
ACTT: 5393.6 Hobbs: 5067.7

PERFORMED THE FOLLOWING MAINTENANCE:

Installed New engine nose crankcase seal P/N 641250. Leak checks good.
Installed New propeller packing P/N C-3317-228. Leak checks good.
Installed New propeller hardware P/N A2044. Ops checks good.

I certify this aircraft has been repaired and inspected in accordance with the current Federal Aviation Regulations and is approved for return to service for the above work accomplished.

Signed: [Signature] W/O No. 10088 CRS No. MXMR954Y Date: 10-13-08



EXECUTIVE AIRSHARE CORPORATION
1600 Airport Road - Mid-Continent Airport
Wichita, Kansas 67209-1996 USA

Make: BEECH Model: A36 S/N: E-959 Reg: N4260S
ACTT: 5493.9 Hobbs: 5169.1 PTT: 464.9

COMPLETED THE FOLLOWING INSPECTIONS:
100 Hr/Annual inspection I.A.W. Beech M.M.

I certify this Propeller has been inspected in accordance with 100 Hr/Annual inspection, in accordance with the current Federal Aviation Regulations was determined to be in airworthy condition and is approved for return to service.

Signed: [Signature] W/O No. 7092 CRS No. MXMR954Y Date: 7-10-09

PROPELLER

SUB-TOTALS this page

TOTALS-Carry forward to next page